

No. 99

Shock Absorber for QUICKLY F, Part-No. 16 57 00 503

Several inquiries from our dealers are the reason for the following data on the functions of the shock absorber.

The operational relationship between spring travel and frequency of motions of the rocker on the QUICKLY F originally resulted in a hydraulic shock absorber having relatively low absorptive power. In addition, the spring guide had to remain accurate.

Now, we are using for the QUICKLY F a shock absorber which meets the various demands and, in addition to a pneumatic effect at reduced energy, guides the spring accurately and provides long life. For this reason the exchange shock absorber No. 16 57 00 900 is no longer carried in stock as an exchange part.

E.

# IceniCAM Information Service

